

1 Department of Conservation, Geologic Energy Management Division
Doug Ito
2 STATE OIL AND GAS SUPERVISOR
715 P Street, MS 19-06 (Legal Office)
3 Sacramento, California 95814
Telephone (916) 323-6733
4
5
6
7

8 **STATE OF CALIFORNIA**
9 **NATURAL RESOURCES AGENCY**
10 **DEPARTMENT OF CONSERVATION**
11 **GEOLOGIC ENERGY MANAGEMENT DIVISION**
12
13

14 **ORDER TO PAY A CIVIL PENALTY AND PERFORM REMEDIAL WORK**
15 **NO. 1502**
16
17

18 **Operator: E&B Natural Resources Management Corporation (E0100)**

19 **Field Names: Cuyama, South and Poso Creek**

20 **Counties: Santa Barbara and Kern**
21
22
23
24
25
26
27
28

I. Introduction

The State Oil and Gas Supervisor (**Supervisor**), acting through the Geologic Energy Management Division (**CalGEM**), and under the authority of Division 3 of the Public Resources Code (**PRC**; commencing with PRC section 3000) and title 14 of the California Code of Regulations (**Regulations**), may impose a civil penalty on a person who violates any statutory provision of the PRC, or any regulation that implements those statutory provisions. (PRC, § 3236.5.)

Based on CalGEM's records, E&B Natural Resources Management Corporation (**Operator**) is the "operator" (as defined in PRC, § 3009) and is responsible for the Wells identified on **Attachment A**, incorporated herein (the "**Wells**"). As described in more detail below, Operator has not maintained compliance with applicable requirements for operation of the Wells. Operator's failure to comply with the Regulations poses a potential threat to life, health, property, and natural resources and constitute violations requiring remedial work and for which the Supervisor has determined imposition of a civil penalty is appropriate. Therefore, pursuant to PRC sections 3106, 3224, 3225, 3226, 3236.5, and 3270 and Regulations section 1777, the Supervisor is ordering Operator to (1) perform remedial work to bring the Wells into compliance and (2) pay an administrative civil penalty for the violations.

Attachment B, incorporated herein, contains a list of definitions and authorities that are applicable to this Order.

II. Alleged Acts and Omissions

Based on CalGEM's records, at all times relevant to this Order, Operator was the operator, as defined in PRC section 3009, of the Wells. On or about October 28, 2024, October 29, 2024, November 5, 2024, November 18, 2024, November 19, 2024, and December 6, 2024, CalGEM conducted inspections of the Wells where the violations described below were observed and documented in the Cuyama, South and Poso Creek Fields. (**Attachments C, D, E, F, G, H, I, and J**, incorporated herein.)

CalGEM records reflect Operator has not maintained compliance with applicable requirements for operation of the Wells. Operator's lack of adherence to the Regulations

poses a potential threat to life, health, property, and natural resources. The violations at issue are identified below.

A. Failure to maintain bolts on wellhead. (Regulations § 1777, subd. (a).)

The wellhead is equipment secured to the upper part of a well, located above the casing and is held in place by a series of bolts. Damaged or missing bolts on the wellhead may lead to leaking around the wellhead. Production facilities include wellheads. (PRC, § 3010; Regulations, § 1760, subd. (r).) Operators are required to maintain production facilities in good condition and in a manner to prevent leakage or corrosion and to safeguard life, health, property, and natural resources and conduct operations in accordance with good oilfield practices. (Regulations, § 1777, subd. (a).)

During the inspection, CalGEM observed bolts missing from the wellhead at the following well, in violation of Regulations, section 1777, subdivision (a):

API	Well Designation
0408300654	S.C.U. 66-6

The one (1) violation was remediated by Operator on or around December 31, 2024.

B. Failure to maintain production facilities in good condition and in a manner to prevent leakage or corrosion. (Regulations, § 1777, subd. (a).)

Operators are required to maintain production facilities in good condition and in a manner to prevent leakage or corrosion and to safeguard life, health, property, and natural resources and conduct operations in accordance with good oilfield practices. (Regulations, § 1777, subd. (a).) Production facilities include wellheads. (PRC, § 3010; Regulations, § 1760, subd. (r).)

During the inspection, CalGEM observed the following wellhead not being maintained in a good condition and in a manner to prevent leakage or corrosion, in violation of the Regulations, section 1777, subdivision (a):

///

///

API	Well Designation
0403064797	Midway Premier 14-2

As of the date of this Order, CalGEM does not have any records from Operator demonstrating that the violation has been corrected.

C. Failure to Keep Well Cellar Drained. (Regulations, § 1777, subd. (c)(3).)

The well cellar is an excavated area around the wellhead that provides space for equipment at the top of the wellbore. Operators are required to keep well cellars drained. (Regulations, § 1777, subd. (c)(3).)

During the inspection, CalGEM observed fluids in the well cellar, in violation of Regulations, section 1777, subd. (c)(3), at the following Wells:

API	Well Designation
0408303228	S.C.U. 31-35
0408303230	S.C.U. 32-1
0408303227	S.C.U. 28-36
0408303183	S.C.U. 68-36
0408303269	S.C.U. 46-6
0408300076	S.C.U. 83-6

The six (6) violations were remediated by Operator on or around December 2, 2024 and December 30, 2024.

III. Civil Penalty/Remedial Work

A. Civil Penalty

Based on the foregoing Alleged Acts and Omissions and pursuant to PRC section 3236.5, by this Order the Supervisor imposes on Operator an administrative civil penalty totaling one thousand eight hundred fifty-five dollars (\$1,855.00) for the eight (8) violations.

///

///

Violation Description	Number of Violations	Associated Civil Penalty per Violation	Civil Penalty Totals
Failure to maintain bolts on wellhead. (Regulations, § 1777, subd. (a).)	1	\$175.00	\$175.00
Failure to Maintain Production Facilities in Good Condition and in a Manner to Prevent Leakage or Corrosion; Leaking Wellheads (Regulations, § 1777, subd. (a).)	1	\$1,000.00	\$1,000.00
Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3).) 0408303228 0408303230 0408303227 0408303183	4	\$100.00	\$400.00
Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3).) 0408303269 0408300076	2	\$140	\$280.00
		Total Civil Penalty:	\$1,855.00

For purposes of this Order, the Supervisor considered relevant circumstances when establishing the amount of the administrative civil penalty, including: characterizing the violations as “minor” (as defined in PRC section 3236.5, subdivision (b)), the eight factors identified in PRC section 3236.5, subdivision (a), and the following: the timeliness by which the violation has been remediated, or not, and the Wells are inside a health protection zone, as defined by Regulations section 1765.1, subdivision (b).

B. Remedial Work

Pursuant to PRC section 3224, the Supervisor hereby orders Operator to complete remedial work to come into compliance with Regulations section 1777, as outlined below in Operator's Required Actions.

IV. Operator's Required Actions

For the reasons stated herein, pursuant to PRC sections 3013, 3106, 3224, 3225, and 3236.5, and Regulations section 1777, **IT IS HEREBY ORDERED** that Operator:

- 1) Pay an administrative civil penalty of one thousand eight hundred fifty-five dollars (\$1,855.00); and
- 2) In accordance with PRC section 3224 and Regulations section 1777 Operator is required to:
 - a. Repair the following wellhead in a manner to prevent leakage or corrosion:

API	Well Designation
0403064797	Midway Premier 14-2

To remit payment of the civil penalty online, please visit <https://www.govone.com/PAYCAL/Home/SelectAgency> and select "California Department of Conservation Geologic Energy Management Division," then follow the instructions on the screen.

To remit payment of the civil penalty by mail, please send a check payable to "Department of Conservation" to the following address:

Department of Conservation
CalGEM, Attn: Operational Management Unit
715 P Street, MS 1803
Sacramento, California 95814

Please include the Operator name, Order number, and phrase "Oil and Gas Environmental Remediation Account" on the check itself.

Upon performing the required remedial work, please contact CalGEM's Central Districts via email at calgemcentralenvironmental@conservation.ca.gov.

///

///

1 **V. Operator's Appeal Rights**

2 Operator may appeal this Order by filing a timely written notice of appeal with the
3 Director as described in Article 6 (Appeals and Review) of Division 3 of the PRC, commencing
4 with PRC section 3350. (PRC, § 3225, subd. (d).) If this Order is mailed to you, the Director must
5 receive the appeal within fifteen (15) days from the date the Supervisor mails the Order. To file
6 an appeal, a written notice of appeal may be sent via U.S. mail to:

7 Department of Conservation

8 Director's Office of Appeals

9 715 P Street, MS 19-06 (Legal Office, Chief Counsel)

10 Sacramento, California 95814

11 Or via electronic mail to:

12 OfficeofAppeals@conservation.ca.gov
13

14 If Operator files a timely written notice of appeal, Operator will be informed of the
15 appeal hearing date, time, and place. Following the hearing, Operator will receive a written
16 decision that affirms, sets aside, or modifies the appealed order.

17 If Operator does not file a timely written notice of appeal, or if the Order is affirmed
18 following an appeal, this Order will become a final order and CalGEM may contract for
19 performance of the work, pursuant to PRC section 3226, if, within 30 days of this Order,
20 Operator has not, in good faith, commenced the work ordered. Any costs incurred by
21 CalGEM to obtain compliance with this Order (which may include penalties and interest) will
22 constitute a lien against Operator's real or personal property per PRC section 3423. (PRC, §
23 3356.)

24 **VI. Other Potential Actions to Enforce This Order**

25 Failure to comply with Section IV (Operator's Required Actions) of this Order could
26 subject Operator to further enforcement action. PRC section 3236 makes it a misdemeanor for
27 any person who violates, fails, neglects, or refuses to comply with any of the provisions of the
28 oil and gas conservation laws commencing at PRC section 3000. PRC sections 3236.2 and

3236.3 authorize the Supervisor to seek for civil penalties and injunctive relief for failure to comply with an order or for violations of any provision in Chapter 1 of Division 3 of the PRC or any regulation that implements those statutes. PRC section 3236.5 authorizes the Supervisor to impose a civil penalty on a person who violates any provision in Chapter 1 of Division 3 of the PRC or any regulation that implements those statutes, and the Supervisor may in the future impose further civil penalties based on the facts and omissions underlying this order. PRC section 3237 authorizes the Supervisor to order the plugging and abandonment of a well or the decommissioning of a production facility if an operator has failed to comply with an order of the Supervisor within the time provided by the order or has failed to challenge the order on a timely basis. PRC section 3359 makes it a misdemeanor to fail or neglect to comply with an order of the Supervisor. Each day's further failure, refusal, or neglect is a separate and distinct offense. (PRC, § 3359.) By issuance of this Order, the Supervisor does not waive the right to take further enforcement actions.

DATED: 2/6/2025

Doug Ito
 Doug Ito
 State Oil and Gas Supervisor